

UNCLAS

SUBJ: INTERIM AUTHORITY TO USE DA FORM 7372 IN LIEU OF THE BLUE COPY OF DA FORM 2407 WHEN UNSERVICEABLE TEST, MEASUREMENT, AND DIAGNOSTIC EQUIPMENT (TMDE) IS BEING TURNED IN

A. DA PAM 710-2-1, USING UNIT SUPPLY SYSTEM (MANUAL PROCEDURES), PARAGRAPH 3-5.

B. DA PAM 710-1-2, SUPPLY SUPPORT ACTIVITY SYSTEM (MANUAL PROCEDURES), PARAGRAPHS 14-3 AND 14-5.

1. REQUEST THIS MESSAGE BE RETRANSMITTED TO ALL SUBORDINATE COMMANDS AND ACTIVITIES
2. A SUGGESTION SUBMITTED UNDER THE ARMY IDEAS FOR EXCELLENCE PROGRAM HAS BEEN APPROVED TO ALLOW UNITS AND ACTIVITIES TURNING IN UNSERVICEABLE TMDE TO USE A COPY OF DA FORM 7372 SHOWING THE CONDITION CODE IN LIEU OF THE BLUE COPY OF THE DA FORM 2407.
3. CURRENT PROCEDURES REQUIRE THE UNIT OR ACTIVITY TO GO BACK TO THEIR UNIT OR ACTIVITY TO OBTAIN AND COMPLETE A DA FORM 2407 WHEN THEY HAVE A PIECE OF TMDE IN FOR CALIBRATION SERVICES AND, DURING CALIBRATION IT IS DETERMINED THE TMDE IS UNSERVICEABLE, UNECONOMICALLY REPAIRABLE UNDER THE REVISED PROCEDURES TO BE PUBLISHED IN DA PAMS 710-2-1 AND 710-2-2, A UNIT OR ACTIVITY MAY USE A COPY OF THE COMPLETED DA FORM 7372 SHOWING THE CONDITION CODE OF THE TMDE IN LIEU OF USING THE BLUE COPY, DA FORM 2407 SHOWING THE CONDITION CODE.
4. INTERIM AUTHORITY IS GRANTED TO IMPLEMENT AND USE THESE PROCEDURES NOW. THESE CHANGES WILL BE INCLUDED IN THE NEXT CHANGE TO DA PAM 710-2-1 AND DA PAM 710-2-2, TENTATIVELY SCHEDULED TO BE PUBLISHED IN 2001.
5. LIA POINT OF CONTACT IS MR. FRED OWEN, DSN 977-7572. E-MAIL ADDRESS IS fred.owen@hqda.army.mil.